

Bridgeboro Historic District Survey 1982

Form 10-920
(June 1983)

UNITED STATES DEPARTMENT OF THE INTERIOR
NATIONAL PARK SERVICE

HABS
NJ,
3-BRIBO,

1/1-

ARCHITECTURAL DATA FORM

STATE New Jersey		COUNTY Burlington	TOWN OR VICINITY Bridgeboro
HISTORIC NAME OF STRUCTURE (INCLUDE SOURCE FOR NAME) Bridgeboro Historic District			HABS NO. NJ-899-1
SECONDARY OR COMMON NAMES OF STRUCTURE Thomas Haines House			
COMPLETE ADDRESS (DESCRIBE LOCATION FOR RURAL SITES) 12 South Bridgeboro Street			
DATE OF CONSTRUCTION (INCLUDE SOURCE) Before 1876 (Scott Atlas, 1876)		ARCHITECT(S) (INCLUDE SOURCE) Unknown	
SIGNIFICANCE (ARCHITECTURAL AND HISTORICAL, INCLUDE ORIGINAL USE OF STRUCTURE) Part of the Bridgeboro Historic District, the most cohesive concentration of nineteenth century buildings in Bridgeboro.			
STYLE (IF APPROPRIATE) Vernacular with Victorian decorative features			
MATERIAL OF CONSTRUCTION (INCLUDE STRUCTURAL SYSTEMS) Wood frame			
SHAPE AND DIMENSIONS OF STRUCTURE (SKETCHED FLOOR PLANS ON SEPARATE PAGES ARE ACCEPTABLE) Rectangular, 21' x 37'. An 8'x8' one-story shed is attached to rear.			
EXTERIOR FEATURES OF NOTE Gable is decorated with fishscale shingles and a round-arched gable window in attic. Side proche with turned columns.			
INTERIOR FEATURES OF NOTE (DESCRIBE FLOOR PLANS, IF NOT SKETCHED) Three-room deep plan with 2 bay side hall front entrance. Living room (front), dining room (middle), kitchen (rear) compose first floor. Second floor consists of three bedrooms with small bath at top of staircase.			
MAJOR ALTERATIONS AND ADDITIONS WITH DATES Rear one-story frame 8'x8' shet attached to rear of building in early twentieth century.			
PRESENT CONDITION AND USE Building vacated on 1/12/81 and presently in dilapidated condition.			
OTHER INFORMATION AS APPROPRIATE			
SOURCES OF INFORMATION (INCLUDING LISTING ON NATIONAL REGISTER, STATE REGISTERS, ETC.) Cultural Resource Survey for Rt. 130, 9F, 2/80, by Historic Sites Research. Real estate appraisal 11/2/79 and interior inspection by compiler on 8/23/82. Determination of eligibility on 6/26/81.			
COMPILER, AFFILIATION Dennis DeGregroy, N.J. Department of Transporation			DATE 9/30/82

Bridgeboro Historic District Survey 1982

HABS
NJ,
3-BRIBO.
1/1-

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

Bridgeboro Historic District
Thomas Haines House
12 South Bridgeboro Street
Bridgeboro
Burlington County
New Jersey

HABS No. NJ-899-1

Photographer: Ken De Blieu

August 1982

NJ-899-1-1 VIEW SOUTHWEST SHOWING EAST AND NORTH (FRONT) ELEVATIONS



Bridgeboro Historic District Survey 1982

UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL ARCHITECTURAL AND ENGINEERING RECORD HISTORIC AMERICAN BUILDINGS SURVEY ARCHITECTURAL DATA FORM		HABS NJ 3-BR180, 172-2	
STATE New Jersey	COUNTY Burlington	TOWN OR VICINITY Bridgeboro-Delran Townships	
HISTORIC NAME OF STRUCTURE (INCLUDE SOURCE FOR NAME) Bridgeboro Historic District Charles Gaskill House (1860 Lake & Beers map of Burlington County)			HABS NO. NJ-899-2
SECONDARY OR COMMON NAMES OF STRUCTURE Langer House (1979)			
COMPLETE ADDRESS (DESCRIBE LOCATION FOR RURAL SITES) 14 South Bridgeboro Street			
DATE OF CONSTRUCTION (INCLUDE SOURCE) Before 1860 (Lake & Beers 1860 Map)		ARCHITECT(S) (INCLUDE SOURCE) Unknown	
SIGNIFICANCE (ARCHITECTURAL AND HISTORICAL, INCLUDE ORIGINAL USE OF STRUCTURE) Part of the Bridgeboro Historic District; the most cohesive concentration of 19th century buildings in Bridgeboro. The property was originally the Charles Gaskill residence in 1860.			
STYLE (IF APPROPRIATE) Vernacular			
MATERIAL OF CONSTRUCTION (INCLUDE STRUCTURAL SYSTEMS) 2½ story wood frame with asphalt shingle siding			
SHAPE AND DIMENSIONS OF STRUCTURE (SKETCHED FLOOR PLANS ON SEPARATE PAGES ARE ACCEPTABLE) Rectangular, 16' width and 38' depth. A 7' width by 11' depth, 1 story frame addition to the west of front and a 1 story 8' by 16' addition in rear.			
EXTERIOR FEATURES OF NOTE A modern, broken pediment over the entrance door.			
INTERIOR FEATURES OF NOTE (DESCRIBE FLOOR PLANS, IF NOT SKETCHED) The first floor consists of a living room in front with a kitchen in the rear. On the second floor are 2 bedrooms and bath. In the rear of the first floor is an efficiency apartment with kitchen downstairs and bedroom and bath upstairs. No interior features of note.			
MAJOR ALTERATIONS AND ADDITIONS WITH DATES For the most part the entire house was renovated in the late 1930's with a 1 story 77 sq. ft. living room addition to the east and a 1 story sq. ft. addition to the rear.			
PRESENT CONDITION AND USE Building vacated on 10/2/80 and is in a state of extreme disrepair.			
OTHER INFORMATION AS APPROPRIATE			
SOURCES OF INFORMATION (INCLUDE LISTING ON NATIONAL REGISTER, STATE REGISTERS, ETC.) Cultural Resource Survey for Rt. 130, 9F, 2/80, by Historic Sites Research. Real estate appraisal on 9/27/79 and interior inspection on 8/24/82. Determination of Eligibility on 6/26/81.			
COMPILER, AFFILIATION Dennis DeGregory, N. J. Department of Transportation			DATE 9/30/82

Bridgeboro Historic District Survey 1982

HISTORIC AMERICAN BUILDING SURVEY

INDEX TO PHOTOGRAPHS

HABS
NJ,
3-BRIBO,

1/2 -

Bridgeboro Historic District
Gaskill, Charles, House
14 South Bridgeboro Street
Bridgeboro
Burlington
NJ

HABS No NJ-899-2

Ken De Blieu Photographer

August, 1982

NJ-899-2-1 3/4 VIEW OF EAST ELEVATION (SIDE) AND NORTH ELEVATION (FRONT)

NJ-899-2-2 INTERIOR VIEW OF LIVINGROOM



Bridgeboro Historic District Survey 1982

Form 10-920 (June 1983)		UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE		HABS NJ, 3-BRIBO. 1/3-	
ARCHITECTURAL DATA FORM					
STATE New Jersey		COUNTY Burlington		TOWN OR VICINITY Bridgeboro	
HISTORIC NAME OF STRUCTURE (INCLUDE SOURCE FOR NAME) Bridgeboro Historic District				HABS NO. NJ-899-3	
SECONDARY OR COMMON NAMES OF STRUCTURE Wallace Lippincott House					
COMPLETE ADDRESS (DESCRIBE LOCATION FOR RURAL SITES) 18-20 South Bridgeboro Street					
DATE OF CONSTRUCTION (INCLUDE SOURCE) Before 1860 (Lake & Beers map, 1860)			ARCHITECT(S) (INCLUDE SOURCE) Unknown		
SIGNIFICANCE (ARCHITECTURAL AND HISTORICAL, INCLUDE ORIGINAL USE OF STRUCTURE) Part of the Bridgeboro Historic District, the most cohesive concentration of nineteenth century buildings in Bridgeboro.					
STYLE (IF APPROPRIATE) Vernacular					
MATERIAL OF CONSTRUCTION (INCLUDE STRUCTURAL SYSTEMS) Wood frame					
SHAPE AND DIMENSIONS OF STRUCTURE (SKETCHED FLOOR PLANS ON SEPARATE PAGES ARE ACCEPTABLE) Rectangular shape, 26'x40'					
EXTERIOR FEATURES OF NOTE Front porch with hip roof and tapered square columns, 6/6 windows in main block of house					
INTERIOR FEATURES OF NOTE (DESCRIBE FLOOR PLANS, IF NOT SKETCHED) Interior floor plan has been altered from semi-detached houses (side by side) to two apartments, one in the main block and one in the rear addition.					
MAJOR ALTERATIONS AND ADDITIONS WITH DATES Dwelling has been modernized throughout, rear wing added					
PRESENT CONDITION AND USE Building vacated on 8/19/80 and presently in a state of disrepair.					
OTHER INFORMATION AS APPROPRIATE					
SOURCES OF INFORMATION (INCLUDING LISTING ON NATIONAL REGISTER, STATE REGISTERS, ETC.) Cultural Resource Survey for Rt. 130, 9F, 2/80, by Historic Sites Research. Real estate appraisal on 9/27/79. Interior inspection on 8/24/82. Determination of eligibility on 6/26/81.					
COMPILER, AFFILIATION Dennis DeGregory, N.J. Department of Transportation				DATE 9/30/82	

Bridgeboro Historic District Survey 1982

HABS
NJ,
3-BRIBO,
1/3-

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

Bridgeboro Historic District
Wallace Lippincott House
18-20 South Bridgeboro Street
Bridgeboro
Burlington County
New Jersey

HABS No. NJ-899-3

Photographer: Ken De Blieu

August 1982

NJ-899-3-1 VIEW SOUTHWEST SHOWING EAST AND NORTH (FRONT) ELEVATIONS

NJ-899-3-2 FIRST FLOOR, STAIRCASE AND INTERIOR WOODWORK



Bridgeboro Historic District Survey 1982



Bridgeboro Historic District Survey 1982

NCRS

United States Department of the Interior
Heritage Conservation and Recreation Service
Washington, DC 20243

NATIONAL ARCHITECTURAL AND ENGINEERING RECORD
HISTORIC AMERICAN BUILDINGS SURVEY
ARCHITECTURAL DATA FORM

HABS
NS,
3-BRIBO,
1/4-

STATE New Jersey	COUNTY Burlington	TOWN OR VICINITY Bridgeboro-Delran Townships
HISTORIC NAME OF STRUCTURE (INCLUDE SOURCE FOR NAME) Ellis Anderson (1876 Atlas of Burlington County) Bridgeboro Historic District		HABS NO. NJ-899-4
SECONDARY OR COMMON NAMES OF STRUCTURE T. Godlewski (1979)		
COMPLETE ADDRESS (DESCRIBE LOCATION FOR RURAL SITES) 22 South Bridgeboro Street		
DATE OF CONSTRUCTION (INCLUDE SOURCE) Prior to 1860	ARCHITECT(S) (INCLUDE SOURCE) Unknown	
SIGNIFICANCE (ARCHITECTURAL AND HISTORICAL, INCLUDE ORIGINAL USE OF STRUCTURE) Part of the Bridgeboro Historic District; the most cohesive concentration of 19th century buildings in Bridgeboro. The property was the residence of Ellis Anderson in 1876.		
STYLE (IF APPROPRIATE) Vernacular		
MATERIAL OF CONSTRUCTION (INCLUDE STRUCTURAL SYSTEMS) 2½ story wood frame with aluminum siding		
SHAPE AND DIMENSIONS OF STRUCTURE (SKETCHED FLOOR PLANS ON SEPARATE PAGES ARE ACCEPTABLE) Rectangular, 24 feet in width by 48 feet in depth.		
EXTERIOR FEATURES OF NOTE None		
INTERIOR FEATURES OF NOTE (DESCRIBE FLOOR PLANS, IF NOT SKETCHED) Two semi-detached dwellings each identical in nature. Three rooms deep with a living room (front), dining room (middle), kitchen (rear), and bath. Second floor consists of two bedrooms.		
MAJOR ALTERATIONS AND ADDITIONS WITH DATES Dwelling modernized throughout.		
PRESENT CONDITION AND USE Building vacated on 11/19/80 and is in poor condition.		
OTHER INFORMATION AS APPROPRIATE		
SOURCES OF INFORMATION (INCLUDE LISTING ON NATIONAL REGISTER, STATE REGISTERS, ETC.) Cultural Resource Survey for Rt. 130, 9F, 2/80, by Historic Sites Research. Real estate appraisal on 10/16/79. Interior inspection on 8/25/82. Determination of Eligibility on 6/26/81.		
COMPILER, AFFILIATION Dennis DeGregory, N. J. Department of Transportation	DATE 9/30/82	

4 OCT 1982

Bridgeboro Historic District Survey 1982

HISTORIC AMERICAN BUILDING SURVEY

INDEX TO PHOTOGRAPHS

Bridgeboro Historic District
Ellis Anderson House
22 South Bridgeboro Street
Bridgeboro
Burlington County
NJ

HABS No NJ-899-4

Ken De Blieu Photographer

August, 1982

NJ-899-4-1 NORTH ELEVATION (FRONT) WEST ELEVATION (SIDE)

NJ-899-4-2 3/4 VIEW SOUTH ELEVATION (REAR) AND EAST ELEVATION (SIDE)

NJ-899-4-3 INTERIOR VIEW OF LIVINGROOM



Bridgeboro Historic District Survey 1982



Bridgeboro Historic District Survey 1982

June 1983		NATIONAL PARK SERVICE		1/3-
ARCHITECTURAL DATA FORM				
STATE New Jersey	COUNTY Burlington	TOWN OR VICINITY Bridgeboro		
HISTORIC NAME OF STRUCTURE (INCLUDE SOURCE FOR NAME) Bridgeboro Historic District			HABS NO. NJ-899-5	
SECONDARY OR COMMON NAMES OF STRUCTURE Aaron Meyers House				
COMPLETE ADDRESS (DESCRIBE LOCATION FOR RURAL SITES) 24 South Bridgeboro Street				
DATE OF CONSTRUCTION (INCLUDE SOURCE) Prior to 1860 (Lake & Beer's Map of 1860)		ARCHITECT(S) (INCLUDE SOURCE) Unknown		
SIGNIFICANCE (ARCHITECTURAL AND HISTORICAL, INCLUDE ORIGINAL USE OF STRUCTURE) Part of the Bridgeboro Historic District, the most cohesive concentration of nineteenth century buildings in Bridgeboro. The property was the residence and millinery shop of Aaron Meyers.				
STYLE (IF APPROPRIATE) Vernacular				
MATERIAL OF CONSTRUCTION (INCLUDE STRUCTURAL SYSTEMS) Wood frame				
SHAPE AND DIMENSIONS OF STRUCTURE (SKETCHED FLOOR PLANS ON SEPARATE PAGES ARE ACCEPTABLE) Rectangular shape, 28' x 25'				
EXTERIOR FEATURES OF NOTE Turned columns on front porch with a cut-out decorative pattern in fascia.				
INTERIOR FEATURES OF NOTE (DESCRIBE FLOOR PLANS, IF NOT SKETCHED) Interior floors have been removed and walls have caved in, preventing an interior inspection. House is in an extremely dilapidated condition.				
MAJOR ALTERATIONS AND ADDITIONS WITH DATES				
PRESENT CONDITION AND USE House was vacated on 1/12/81 and is in ruinous, dilapidated condition.				
OTHER INFORMATION AS APPROPRIATE				
SOURCES OF INFORMATION (INCLUDING LISTING ON NATIONAL REGISTER, STATE REGISTERS, ETC.) Cultural Resource Survey for Rt. 130, 9F, 2/80, by Historic Sites Research. Real estate appraisal on 10/1/79. Field inspection on 8/25/82. Determination of Eligibility on 6/26/81.				
COMPILER, AFFILIATION Dennis DeGregroy, N.J. Department of Transportation			DATE 9/30/82	

Bridgeboro Historic District Survey 1982

HABS
NJ,
3-BRIBO,
1/5-

HISTORIC AMERICAN BUILDINGS SURVEY
INDEX TO PHOTOGRAPHS

Bridgeboro Historic District
Aaron Meyers House
24 South Bridgeboro Street
Bridgeboro
Burlington County
New Jersey

HABS No. NJ-899-5

Photographer: Ken De Blieu

August 1982

NJ-899-5-1 VIEW SOUTHWEST SHOWING EAST AND NORTH (FRONT) ELEVATIONS
NJ-899-5-2 VIEW EAST SHOWING WEST ELEVATION
NJ-899-5-3 VIEW NORTHWEST SHOWING SOUTH (REAR) AND EAST ELEVATIONS



Bridgeboro Historic District Survey 1982



Bridgeboro Historic District Survey 1982

<p>RECORDS</p> <p>United States Department of the Interior Heritage Conservation and Recreation Service Washington, DC 20243</p>		<p>NATIONAL ARCHITECTURAL AND ENGINEERING RECORD HISTORIC AMERICAN BUILDINGS SURVEY ARCHITECTURAL DATA FORM</p> <p>HABS NJ 3-BR, 130, 1/6-</p>	
STATE New Jersey	COUNTY Burlington	TOWN OR VICINITY Bridgeboro-Delran Townships	
HISTORIC NAME OF STRUCTURE (INCLUDE SOURCE FOR NAME) Bridgeboro Historic District Widow Fannie Bright (1876 Scott Atlas)			HABS NO. NJ-899-6
SECONDARY OR COMMON NAMES OF STRUCTURE M. Moreland (1979)			
COMPLETE ADDRESS (DESCRIBE LOCATION FOR RURAL SITES) 26 South Bridgeboro Street			
DATE OF CONSTRUCTION (INCLUDE SOURCE) Prior to 1876 (1876 Scott Atlas)		ARCHITECT(S) (INCLUDE SOURCE) Unknown	
SIGNIFICANCE (ARCHITECTURAL AND HISTORICAL, INCLUDE ORIGINAL USE OF STRUCTURE) Part of the Bridgeboro Historic District; the most cohesive concentration of 19th century buildings in Bridgeboro. The property was the residence of Widow Fannie Bright in 1876.			
STYLE (IF APPROPRIATE) Vernacular			
MATERIAL OF CONSTRUCTION (INCLUDE STRUCTURAL SYSTEMS) 2 1/2 story wood frame with wood clapboard siding			
SHAPE AND DIMENSIONS OF STRUCTURE (SKETCHED FLOOR PLANS ON SEPARATE PAGES ARE ACCEPTABLE) Rectangular shape with a 27-foot width and 36-foot depth. A one-story addition being 12 feet deep by 14 feet wide is at the rear of the building.			
EXTERIOR FEATURES OF NOTE None			
INTERIOR FEATURES OF NOTE (DESCRIBE FLOOR PLANS, IF NOT SKETCHED) A 3 bay side hall plan being 3 rooms deep. First floor consists of a living room, dining room, sitting room, and kitchen in the rear. Second level has three bedrooms and a bath. Exceptionally nice newel post and balaster.			
MAJOR ALTERATIONS AND ADDITIONS WITH DATES Rear one-story 12-foot by 14-foot kitchen addition sometime in the early 20th century.			
PRESENT CONDITION AND USE Vacated on 2/4/81 and is in good condition.			
OTHER INFORMATION AS APPROPRIATE			
SOURCES OF INFORMATION (INCLUDE LISTING ON NATIONAL REGISTER, STATE REGISTERS, ETC.) Cultural Resource Survey for Rt. 130, 9F, 2/80, by Historic Sites Research. Real estate appraisal on 11/2/79. Field inspection on 8/25/82. Determination of Eligibility on 6/26/81.			
COMPILER, AFFILIATION Dennis DeGregory, N. J. Department of Transportation			DATE 9/30/82

4 OCT 1982

Bridgeboro Historic District Survey 1982

HABS
NJ,
3-BRIBO,
1/6-

HISTORIC AMERICAN BUILDING SURVEY
INDEX TO PHOTOGRAPHS

Bridgeboro Historic District, Widow Fannie Bright House HABS NO NJ-899-6
26 South Bridgeboro Street
Bridgeboro
Burlington County
NJ

Ken De Bieu Photographer August, 1982

NJ-899-6-1 NORTH ELEVATION (FRONT)

NJ-899-6-2 3/4 VIEW WEST ELEVATION (SIDE) AND SOUTH ELEVATION (REAR)

NJ-899-6-3 INTERIOR VIEW DETAIL OF NEWEL POST AND BALUSTRADE



Bridgeboro Historic District Survey 1982



Bridgeboro Historic District Survey 1982

Form 10-920 (June 1983)		UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE		HABS NJ, 3-BRIBO, 1/1-	
ARCHITECTURAL DATA FORM					
STATE New Jersey		COUNTY Burlington		TOWN OR VICINITY Bridgeboro	
HISTORIC NAME OF STRUCTURE (INCLUDE SOURCE FOR NAME) Bridgeboro Historic District					HABS NO. NJ-899-7
SECONDARY OR COMMON NAMES OF STRUCTURE 28 South Bridgeboro Street (House)					
COMPLETE ADDRESS (DESCRIBE LOCATION FOR RURAL SITES) 28 South Bridgeboro Street					
DATE OF CONSTRUCTION (INCLUDE SOURCE) After 1876 (Scott Atlas)			ARCHITECT(S) (INCLUDE SOURCE) Unknown		
SIGNIFICANCE (ARCHITECTURAL AND HISTORICAL, INCLUDE ORIGINAL USE OF STRUCTURE) Part of the Bridgeboro Historic District, the most cohesive concentration of nineteenth century buildings in Bridgeboro. The property was a residence built after 1876.					
STYLE (IF APPROPRIATE) Vernacular with Victorian decorative features.					
MATERIAL OF CONSTRUCTION (INCLUDE STRUCTURAL SYSTEMS) Wood frame					
SHAPE AND DIMENSIONS OF STRUCTURE (SKETCHED FLOOR PLANS ON SEPARATE PAGES ARE ACCEPTABLE) Rectangular in shape, 29' x 42'					
EXTERIOR FEATURES OF NOTE Cross gable roof, turned posts on side porch, round-arched windows in attic gable ends					
INTERIOR FEATURES OF NOTE (DESCRIBE FLOOR PLANS, IF NOT SKETCHED) Interior has been altered to accommodate two apartments, 1 on first floor and 1 on second. First floor consists of kitchen, 2 bedrooms, living room, and utility room. Second floor has a living room, dining room, kitchen, and 2 bedrooms.					
MAJOR ALTERATIONS AND ADDITIONS WITH DATES One story shed 10' x 12' at rear of building and one story lean-to off the side of front. Both are twentieth century additions.					
PRESENT CONDITION AND USE Good condition, residential use.					
OTHER INFORMATION AS APPROPRIATE					
SOURCES OF INFORMATION (INCLUDING LISTING ON NATIONAL REGISTER, STATE REGISTERS, ETC.) Cultural Resource Survey for Rt. 130, 9F, 2/80, by Historic Sites Research. Real estate appraisal 9/24/79. Field inspection 8/26/82. Determination of Eligibility 6/26/81.					
COMPILER, AFFILIATION Dennis DeGregory, N.J. Department of Transportation					DATE 9/30/82

Bridgeboro Historic District Survey 1982

HABS
NJ,
3-BRIBO,
1/7-

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

Bridgeboro Historic District
28 South Bridgeboro Street (House)
Bridgeboro
Burlington County
New Jersey

HABS No. NJ-899-7

Photographer: Ken De Blieu

August 1982

NJ-899-7-1 VIEW SOUTHWEST SHOWING NORTH (FRONT) ELEVATION

NJ-899-7-2 VIEW NORTHWEST SHOWING EAST ELEVATION



Bridgeboro Historic District Survey 1982



Bridgeboro Historic District Survey 1982

NATIONAL ARCHITECTURAL AND ENGINEERING RECORD HISTORIC AMERICAN BUILDINGS SURVEY ARCHITECTURAL DATA FORM		HABS NJ, 3-BRIBO, 118-
United States Department of the Interior Heritage Conservation and Recreation Service Washington, DC. 20243		
STATE New Jersey	COUNTY Burlington	TOWN OR VICINITY Bridgeboro-Delran Townships
HISTORIC NAME OF STRUCTURE (INCLUDE SOURCE FOR NAME) Andrew Ridgeway (1876 Scott Atlas) Bridgeboro Historic District		HABS NO. NJ-899-8
SECONDARY OR COMMON NAMES OF STRUCTURE Mrs. French House (1979)		
COMPLETE ADDRESS (DESCRIBE LOCATION FOR RURAL SITES) 30 South Bridgeboro Street		
DATE OF CONSTRUCTION (INCLUDE SOURCE) Before 1876 (1876 Scott Atlas)	ARCHITECT(S) (INCLUDE SOURCE) Unknown	
SIGNIFICANCE (ARCHITECTURAL AND HISTORICAL, INCLUDE ORIGINAL USE OF STRUCTURE) Part of the Bridgeboro Historic District; the most cohesive concentration of 19th century buildings in Bridgeboro. The property was a residence built before 1876.		
STYLE (IF APPROPRIATE) Vernacular		
MATERIAL OF CONSTRUCTION (INCLUDE STRUCTURAL SYSTEMS) 2½ story wood frame with asbestos siding		
SHAPE AND DIMENSIONS OF STRUCTURE (SKETCHED FLOOR PLANS ON SEPARATE PAGES ARE ACCEPTABLE) Rectangular, 28 feet wide by 45 feet deep.		
EXTERIOR FEATURES OF NOTE None		
INTERIOR FEATURES OF NOTE (DESCRIBE FLOOR PLANS, IF NOT SKETCHED) First floor consists of a center hall staircase, living room, dining room, kitchen, sitting room, and shed. The second floor consists of three bedrooms and a bath. There are no interior features of note.		
MAJOR ALTERATIONS AND ADDITIONS WITH DATES Rear shed 16 feet by 8 feet built in early 20th century.		
PRESENT CONDITION AND USE Unoccupied since 10/28/80 and is in good condition.		
OTHER INFORMATION AS APPROPRIATE		
SOURCES OF INFORMATION (INCLUDE LISTING ON NATIONAL REGISTER, STATE REGISTERS, ETC.) Cultural Resource Survey for Rt. 130, 9F, 2/80, by Historic Sites Research. Real estate appraisal 11/2/79. Field inspection 8/26/82. Determination of eligibility on 6/26/81.		
COMPILER, AFFILIATION Dennis DeGregory, N. J. Department of Transportation		DATE 9/30/82

Bridgeboro Historic District Survey 1982

HABS
NJ,
3-BRIBO,
1/8-

HISTORIC AMERICAN BUILDING SURVEY
INDEX TO PHOTOGRAPHS

Bridgeboro Historic District, Andrew Ridgeway House
30 South Bridgeboro Street
Bridgeboro
Burlington County
NJ

HABS No NJ-899-8

Ken De Blieu Photographer August, 1982

NJ-899-8-1 NORTH ELEVATION (FRONT) AND WEST ELEVATION (SIDE)

NJ-899-8-2 3/4 VIEW SOUTH ELEVATION (REAR) AND WEST ELEVATION (SIDE)

NJ-899-8-3 INTERIOR VIEW OF NEWEL POST AND BALUSTRADE



Bridgeboro Historic District Survey 1982



Bridgeboro Historic District Survey 1982

UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL SYSTEM OF PUBLIC LANDS Heritage Conservation and Recreation Service Washington, DC 20243		NATIONAL ARCHITECTURAL AND ENGINEERING RECORD HISTORIC AMERICAN BUILDINGS SURVEY ARCHITECTURAL DATA FORM		HABS NJ 3-BRIBO, 1/9-
STATE New Jersey	COUNTY Burlington	TOWN OR VICINITY Bridgeboro-Delran Townships		
HISTORIC NAME OF STRUCTURE (INCLUDE SOURCE FOR NAME) Bridgeboro Historic District 32-34 South Bridgeboro Street (Apartment House)			HABS NO. NJ-899-9	
SECONDARY OR COMMON NAMES OF STRUCTURE F. Ott (1979)				
COMPLETE ADDRESS (DESCRIBE LOCATION FOR RURAL SITES) 32-34 South Bridgeboro Street				
DATE OF CONSTRUCTION (INCLUDE SOURCE) 1910		ARCHITECT(S) (INCLUDE SOURCE) Unknown		
SIGNIFICANCE (ARCHITECTURAL AND HISTORICAL, INCLUDE ORIGINAL USE OF STRUCTURE) Part of the Bridgeboro Historic District, the most cohesive concentration of 19th century buildings in Bridgeboro. The property was an apartment building.				
STYLE (IF APPROPRIATE) Early 20th century vernacular				
MATERIAL OF CONSTRUCTION (INCLUDE STRUCTURAL SYSTEMS) Masonry load bearing wall				
SHAPE AND DIMENSIONS OF STRUCTURE (SKETCHED FLOOR PLANS ON SEPARATE PAGES ARE ACCEPTABLE) Rectangular shape 28 feet wide by 51 feet deep				
EXTERIOR FEATURES OF NOTE Cast stone walls				
INTERIOR FEATURES OF NOTE (DESCRIBE FLOOR PLANS, IF NOT SKETCHED) This four-family apartment house consists of a living room, dining room, kitchen, one bedroom and bath in each unit.				
MAJOR ALTERATIONS AND ADDITIONS WITH DATES Rear one-story frame enclosed porch 5 feet deep by 12 feet wide constructed in the mid 20th century.				
PRESENT CONDITION AND USE Occupied and in good condition.				
OTHER INFORMATION AS APPROPRIATE				
SOURCES OF INFORMATION (INCLUDE LISTING ON NATIONAL REGISTER, STATE REGISTERS, ETC.) Cultural Resource Survey for Rt. 130, 9F, 2/80, by Historic Sites Research. Real estate appraisal on 11/30/79. Field inspection on 8/26/82. Determination of eligibility on 6/26/81.				
COMPILER, AFFILIATION Dennis DeGregory, N. J. Department of Transportation			DATE 9/30/82	

Bridgeboro Historic District Survey 1982

HABS
NJ,
3-BRIBO,
1/9-

~~BRIBO~~
~~FN~~
~~HABS~~

HISTORIC AMERICAN BUILDING SURVEY
INDEX TO PHOTOGRAPHS

Bridgeboro Historic District
33-34 South Bridgeboro Street, (Apartment House)
Bridgeboro
Burlington County
NJ

HABS No NJ-899-9

Ken De Blieu Photographer August, 1982

NJ-899-9-1 3/4 VIEW OF EAST ELEVATION (SIDE) AND NORTH ELEVATION (FRONT)

NJ-899-9-2 3/4 VIEW WEST ELEVATION (SIDE) AND SOUTH ELEVATION (REAR)



Bridgeboro Historic District Survey 1982



Bridgeboro Historic District Survey 1982

RECORDS United States Department of the Interior Heritage Conservation and Recreation Service Washington, D.C. 20243		NATIONAL ARCHITECTURAL AND ENGINEERING RECORD HISTORIC AMERICAN BUILDINGS SURVEY HABS NJ 3-BR189 1/11- ARCHITECTURAL DATA FORM	
STATE New Jersey	COUNTY Burlington	TOWN OR VICINITY Bridgeboro-Delran Townships	
HISTORIC NAME OF STRUCTURE (INCLUDE SOURCE FOR NAME) J. S. Lowden House (1860 Lake & Beers Map of Burlington County). Bridgeboro Historic District		HABS NO. NJ-899-11	
SECONDARY OR COMMON NAMES OF STRUCTURE Maudean Keys House			
COMPLETE ADDRESS (DESCRIBE LOCATION FOR RURAL SITES) Route 130, Bridgeboro - Route 130, Section 9F Parcel 160			
DATE OF CONSTRUCTION (INCLUDE SOURCE) Before 1860 (1860 Map of Lake & Beers)		ARCHITECT(S) (INCLUDE SOURCE) Unknown	
SIGNIFICANCE (ARCHITECTURAL AND HISTORICAL, INCLUDE ORIGINAL USE OF STRUCTURE) Part of the Bridgeboro Historic District; a property determined eligible for inclusion to the National Register by the Keeper of the National Register on 6/26/81. The Bridgeboro Historic District is significant as the most cohesive concentration of 19th century buildings in Bridgeboro. (House is a residence of J. S. Lowden.)			
STYLE (IF APPROPRIATE) Vernacular			
MATERIAL OF CONSTRUCTION (INCLUDE STRUCTURAL SYSTEMS) 2 story wood frame dwelling with asphalt shingle siding			
SHAPE AND DIMENSIONS OF STRUCTURE (SKETCHED FLOOR PLANS ON SEPARATE PAGES ARE ACCEPTABLE) The rectangular 2 bay 2½ story side hall with entrance door in northern bay is approximately 14½ feet wide by 24 feet in depth. A 1 story lean-to kitchen addition 18 feet			
EXTERIOR FEATURES OF NOTE wide by 10 feet deep is attached to the rear. No noteworthy exterior conditions exist due to its present vandalized condition upon inspection on 8/23/82.			
INTERIOR FEATURES OF NOTE (DESCRIBE FLOOR PLANS, IF NOT SKETCHED) Two-room deep plan with living room (front) and dining room (rear) bisected by a fireplace with wraparound pie-shaped staircase. Lean-to kitchen to rear of dining room. The second floor consists of 2 bedrooms. No interior features of note.			
MAJOR ALTERATIONS AND ADDITIONS WITH DATES Not applicable.			
PRESENT CONDITION AND USE Presently vacated since 10/80. Condition is extremely poor and dilapidated.			
OTHER INFORMATION AS APPROPRIATE			
SOURCES OF INFORMATION (INCLUDE LISTING ON NATIONAL REGISTER, STATE REGISTERS, ETC.) Cultural Resource Survey for Rt. 130, 9F, 2/80, by Historic Sites Research. Real estate appraisal 9/24/79 and interior inspection on 8/23/82. Determination of Eligibility on 6/26/81.			
COMPILER, AFFILIATION Dennis DeGregory, N. J. Department of Transportation			DATE 9/30/82

4 OCT 1982

Bridgeboro Historic District Survey 1982

HISTORIC AMERICAN BUILDING SURVEY

INDEX TO PHOTOGRAPHS

HABS
NJ,
3-BRIBO,
1/11 -

Bridgeboro Historic District
J.S. Lowden House
Route 130, Section 9F Parcel 160
Bridgeboro
Burlington County
NJ

HABS No NJ-899-11

Ken De Blieu Photographer

August, 1982

NJ-899-11-1 NORTH (SIDE), WEST ELEVATION (FRONT)

NJ-899-11-2 SOUTH (SIDE) AND EAST ELEVATION (REAR)

NJ-899-11-3 INTERIOR VIEW OF STAIR CASE



Bridgeboro Historic District Survey 1982



Bridgeboro Historic District Survey 1982